



WET AREA CALL POINT  
MOMENTARY MODE



WET AREA CALL POINT  
LATCHING MODE



NOTES:

1. SCOTCHLOKS AND SILICON MUST BE USED TO ENSURE WATER SEAL
2. STAINLESS STEEL CLIPSAL SCREWS CAPPED WITH SILICON MUST BE USED FOR MOUNTING
3. SEAL SPARE WIRES WITH SCOTCHLOKS